

Vector Control and Dynamics of AC Drives

D. W. Novotny and T. A. Lipo

*Department of Electrical and Computer Engineering
University of Wisconsin-Madison
Wisconsin, USA*



CLARENDON PRESS • OXFORD

CONTENTS

<i>1 Introduction to AC Drives</i>	.1
1.1 Introduction	1
1.2 Review of DC Drives	2
1.3 Comparison of DC and AC Motor Drives	4
1.3.1 Commutator and Brushes	4
1.3.2 Power vs. Speed Range	5
1.3.3 Efficiency	5
1.3.4 Power Factor	5
1.3.5 Inertia	6
1.3.6 Protection	6
1.3.7 Motor Maintenance	6
1.3.8 Ruggedness	6
1.3.9 Standstill Performance	7
1.3.10 Size and Weight	7
1.4 Comparison of Synchronous and Induction Machines	7
1.5 Inverters for Adjustable Speed	9
1.6 The Six Step Voltage Stiff Inverter (VSI)	9
1.7 Six Step Inverter Speed and Slip Frequency Control Techniques . .	15
1.8 The Pulse Width Modulated Inverter (PWM)	18
1.8.1 Block Modulation	19
1.8.2 Sinusoidal PWM Modulation	20
1.8.3 Synchronous vs. Asynchronous Modulation	21
1.8.4 Pulse Dropping	23
1.8.5 Changeover to Six Step Mode	24
1.8.6 Losses Caused by Inverters	24
1.8.7 Torque Pulsations	25
1.8.8 Induction Motor Speed Control Using a PWM Inverter	25
1.9 The Current Stiff Inverter (CSI)	25
1.10 High Performance Drives vs. General Purpose Drives	31
References	33
<i>2 d,q Modelling of Induction and Synchronous Machines</i>	35
2.1 Introduction	35
2.2 Winding Inductances	35

CONTENTS

2.3	System Equations in the Stationary a,b,c Reference Frame	43
2.4	Determination of Induction Machine Inductances	45
2.5	Complex Vector Representation of Three Phase Variables	48
2.6	Complex Variable Model of Three Phase Induction Machine	52
2.7	Turns Ratio Transformation	54
2.8	Transformation to a Rotating Reference Frame	56
2.9	Interpretation of Complex Vectors	61
2.10	Power Flow in the d,q Equivalent Circuit	68
2.11	Example - Stator a,b,c and Rotor d,q Model (Stator Referred)	70
2.12	The Electromagnetic Torque	73
2.13	Analysis of Induction Motor Starting Performance Using $d,q,0$ Variables	78
2.14	Extension of $d,q,0$ Theory to Analysis of Salient Pole Synchronous Machines	88
2.15	Extension of $d, q,0$ Theory to Analysis of Permanent Magnet Motors	102
	References	103
	Problems	105
3	<i>d,q Models for Solid State Power Converters</i>	109
3.1	Introduction	109
3.2	d,q Model for Voltage Source Inverter	109
3.3	d,q Model for PWM Operation	115
3.4	d,q Model for CSI System	116
3.5	Inverter d,q Models in a Synchronous Reference Frame	120
3.6	Examples of Inverter-Induction Motor Models	123
3.7	Fundamental Component Approximation for Steady State Operation	132
3.8	Duality of VSI and CSI Systems	144
	References	145

CONTENTS

Problems	146
4 Complex Vector Analysis of Induction Machines.....	151
4.1 Introduction	151
4.2 Complex Vector Equivalent Circuit	152
4.3 Turns Ratio and Modified d,q Models	153
4.4 Steady State Equivalent Circuits	156
4.4.1 Sinusoidal Excitation in Complex Vector Form	156
4.4.2 Stator Referred Equivalent Circuits	158
4.5 Invariance of the Steady State Equivalent Circuit	164
4.6 Modified Equivalent Circuits	165
4.7 Electrical Transients at Constant Speed	170
4.7.1 Complex Vector Operational Impedances	171
4.7.2 Example - Sudden Application of Stator Current Source Excitation	172
4.7.3 General Solution for Switching Transients	177
4.8 The Constant Speed Eigenvalues	177
4.8.1 Example - Sudden Short Circuit of Unloaded Induction Machine	187
4.9 Transient Equivalent Circuits (Constant Rotor Flux Linkage)	190
4.9.1 Constant Rotor Flux Linkage Model	190
4.9.2 Transient Equivalent Circuit	191
4.9.3 Evaluation of Voltage Behind Transient Reactance	192
4.9.4 Example - Sudden Short Circuit of Unloaded Induction Machine	194
4.9.5 Comments on the Transient Equivalent Circuit	196
References	196
Problems	198
5 Principles of Vector Control and Field Orientation	203
5.1 Introduction	203
5.2 DC Machine Torque Control	203
5.3 Requirements for Torque Control	206
5.4 Synchronous Machine Vector Control	208
5.4.1 CSI - Synchronous Machine (Commutatorless DC Machine)	208
5.4.2 Torque Control and Choice of y	212

CONTENTS

5.5	Synchronous Machine Steady State d,q Model	213
5.5.1	Steady State Conditions in d,q Variables	213
5.5.2	d,q Variable Vector Diagrams	214
5.6	Torque Control Implementations - Synchronous Machines	217
5.6.1	Torque Control Using Field Orientation with a CSI	217
5.6.2	Torque Control Using a CRPWM	218
5.6.3	Magnitude - Angle Resolver and Use in CSI Torque Control	220
5.6.4	Torque Control Requirements - Synchronous Machine	221
5.7	Electrical Measurement of the Rotor Field Angle 9 _r	222
5.8	Brushless DC Machines	222
5.8.1	Sine Wave Machines with Current Control	223
5.8.2	Trapezoidal Wave Machines with Current Control	224
5.8.3	Other Brushless Machines	225
5.9	Induction Machine Vector Control — Steady State	226
5.9.1	Conventional Equivalent Circuit Considerations	226
5.9.2	Modified Equivalent Circuit	228
5.9.3	Torque Control in Terms of $I_{st\geq}$ and $I_{st\leq}$	230
5.9.4	Terminal Behavior in Terms of $/^\wedge$ and I_{st}	233
5.10	Induction Machine Steady State d,q Model	234
5.10.1	Example - Induction Machine Field Orientation	235
5.11	Implementation of Field Orientation in Induction Machines	240
5.11.1	Indirect Field Orientation	241
5.11.2	Direct Field Orientation	247
5.11.3	Torque Control Requirements	247
5.12	A Basic Difference Between Synchronous and Induction Machine Field Orientation	249
	References	250
	Problems	252
6	Dynamics of Vector Control and Field Orientation	257
6.1	Introduction	257
6.2	Dynamics of Induction Machine Field Orientation	257
6.2.1	Induction Machine d,q Model with Axis Rotation at an Angular Velocity ω_0	258
6.2.2	Rotor Flux Referred Equations	258
6.2.3	Dynamic Response of Field Oriented Induction Machines	260

CONTENTS

6.2.4	Block Diagram of Field Oriented Induction Machine	263
6.3	Indirect Controllers for Induction Machine Field Orientation	264
6.3 A	Indirect Controller with \dot{i}_s^* and \dot{f}^* as Inputs	265
6.3.2	Indirect Controller with K^r and i^* as Inputs	265
6.3.3	Other Indirect Controllers	267
6.3.4	Indirect Control Using a CSI	268
6.3.5	Indirect Field Orientation Start Up Transient	269
6.4	Direct Controllers for Induction Machine Field Orientation	275
6.4.1	Direct Determination of Rotor Flux Angle	276
6.4.2	Measurement of Air Gap Flux	276
6.4.3	Voltage and Current Sensing	278
6.4.4	Implementation of Direct Field Orientation	280
6.5	Induction Machine Field Orientation Using Air Gap Flux	282
6.5.1	Air Gap Flux Referred d,q Equations	283
6.5.2	Dynamic Response of Air Gap Flux Controlled Induction Machine	284
6.5.3	Steady State Interpretation of Air Gap Flux Control	286
6.5.4	Indirect Field Orientation Controller for Air Gap Flux	287
6.5.5	Direct Field Orientation Controller for Air Gap Flux	288
6.6	Dynamics of Synchronous Machine Vector Control and Field Orientation	290
6.6.1	d,q Model of Synchronous Machine	290
6.6.2	Vector Control and Angle Control	291
6.6.3	Dynamics of Synchronous Machine Field Orientation	293
6.6.3.1	Constant Field Current Operation (Constant Torque Region)	293
6.6.3.2	Variable Field Excitation (Field Weakening Region)	295
6.6.4	Dynamic Response With θ^* (Angle Control)	296
6.6.5	Example - Synchronous Machine Field Orientation	298
6.7	Field Orientation Using Voltage as the Controlled Variable	304
6.7.1	Stator Voltage Equations in Terms of Rotor Flux - Induction Machine	304
6.7.2	Decoupling Equations for Field Orientation	305
6.7.3	Examples of Field Orientation Using Voltage Controlled Inverters	308
6.8	Stator Flux Based Field Orientation	309
6.8.1	Mathematical Model of a Stator Flux Oriented Induction Machine	310
6.8.2	Design of a Decoupler for Direct Stator Flux Oriented System	311
	References	313
	Problems	315

CONTENTS

<i>7 Current Regulation in Power Converters</i>	<i>317</i>
7.1 Introduction	317
7.2 Current Regulated Inverters	317
7.2.1 The Current Regulated CSI Inverter	318
7.2.2 The Current Regulated PWM Inverter	321
7.3 Hysteresis Regulators	322
7.4 Ramp-Comparison Controllers	331
7.5 Stationary Frame Regulators	335
7.6 Synchronous Frame Regulators	340
7.7 Feedforward Compensation	344
7.8 Augmented Feedforward Compensation	347
7.9 Augmented Feedforward Compensation with Decoupling	348
7.10 Predictive Control	349
7.11 Conclusion	351
References	351
Problems	352
<i>8 Parameter Sensitivity and Saturation Effects in Indirect Field Orientation</i>	<i>353</i>
8.1 Introduction	353
8.2 Phasor Diagram for Detuned Operation	353
8.2.1 Field Orientation Torque Characteristics	355
8.2.2 Examples	361
8.2.3 Field Orientation Flux Characteristics	363
8.2.4 Influence of Saturation	364
8.2.5 Power Loss Considerations	365
8.2.6 Example — Detuned Induction Machine Field Orientation	369
8.3 Transient Response	377
8.3.1 Torque Response with Slip Gain Error	377
8.3.2 Block Diagram Representation of Slip Gain Error	383
8.3.3 Simulation of Transient Response with Slip Gain Error	384

CONTENTS

8.4	Optimal Selection of Flux Level	388
8.4.1	Maximum Torque Per Stator Ampere	389
8.4.2	Maximum Drive Efficiency	390
8.4.3	Reduced Sensitivity to Controller Detuning	393
8.4.4	Optimal Utilization of the Converter	394
8.4.4.1	Converter Current Limits	394
8.4.4.2	Converter Current and Voltage Limits	395
	References	397
	Problems	398
 <i>9 Field Weakening Operation</i>		<i>401</i>
9.1	Introduction	401
9.2	Torque Demand and Availability of High Performance Drives	402
9.3	Induction Machine Control Strategy for Constant Horsepower Operation	405
9.4	Inverter Imposed Voltage and Current Limits	406
9.5	Maximum Torque Capability Curve Using the Conventional Method	409
9.6	Scheme for Achieving Maximum Torque Capability	410
9.6.1	Transition from Constant Torque to Constant Power Operation	411
9.6.2	Region #2 - Field Weakening with Constant Output Power	412
9.6.3	Region #3 - Field Weakening with Constant Speed*Power	413
9.7	Control System Implementation	414
	References	416
<i>Appendix - per Unit Representation</i>		<i>417</i>
<i>Answers to Problems</i>		<i>419</i>
 <i>Index</i>		<i>435</i>