

# DEFORMATION- MECHANISM MAPS

The Plasticity and Creep of Metals and Ceramics

By

H. J. FROST

Dartmouth College, New Hampshire, USA

and

M. F. ASHBY

Cambridge University, UK



PERGAMON PRESS

OXFORD · NEW YORK · TORONTO · SYDNEY · PARIS · FRANKFURT

## CONTENTS

1	Deformation Mechanisms and Deformation-mechanism Maps	1
2	Rate-equations	6
3	Construction of the Maps	17
4	The f.c.c. Metals: Ni, Cu, Ag, Al, Pb and $\gamma$ -Fe	20
5	The b.c.c. Transition Metals: W, V, Cr, Nb, Mo, Ta, and $\alpha$ -Fe	30
6	The Hexagonal Metals: Zn, Cd, Mg and Ti	43
7	Non-ferrous Alloys: Nichromes, T-D Nickels and Nimonics	53
8	Pure Iron and Ferrous Alloys	60
9	The Covalent Elements, Si and Ge	71
10	The Alkali Halides: NaCl and LiF	75
11	The Transition-metal Carbides: ZrC and TiC	80
12	Oxides with the Rock-salt Structure: MgO, CoO and FeO	84
13	Oxides with the Fluorite Structure: UO <sub>2</sub> and ThO <sub>2</sub>	93
14	Oxides with the $\alpha$ -Alumina Structure: Al <sub>2</sub> O <sub>3</sub> , Cr <sub>2</sub> O <sub>3</sub> and Fe <sub>2</sub> O <sub>3</sub>	98
15	Olivines and Spinel: Mg <sub>2</sub> SiO <sub>4</sub> and MgAl <sub>2</sub> O <sub>4</sub>	105
16	Ice, H <sub>2</sub> O	111
17	Further Refinements: Transient Behaviour; Very High and Very Low Strain Rates; High Pressure	117
18	Scaling Laws and Isomechanical Groups	133
19	Applications of Deformation-mechanism Maps	141
	Materials Index	163
	Subject Index	165