

Introduction to  

---

Statistical  

---

Quality  

---

Control  

---

Third Edition

Douglas C. Montgomery  
*Arizona State University*



John Wiley & Sons, Inc.  
New York • Chichester • Brisbane • Toronto • Singapore

# Contents

---

<b>CHAPTER 1</b>	<b>QUALITY IMPROVEMENT IN THE MODERN BUSINESS ENVIRONMENT</b>	<b>1</b>
1-1	The Meaning of Quality and Quality Improvement	2
1-1.1	Dimensions of Quality	2
1-1.2	Quality Engineering Terminology	6
1-2	A Brief History of Quality Methodology	8
1-3	Statistical Methods for Quality Improvement	12
1-4	Total Quality Management	17
1-4.1	Quality Philosophy	17
1-4.2	The Link Between Quality and Productivity	21
1-4.3	Quality Costs	22
1-4.4	Legal Aspects of Quality	28
1-4.5	Implementing Quality Improvement	30
<hr/>		
<b>PART I</b>	<b>STATISTICAL METHODS USEFUL IN QUALITY IMPROVEMENT</b>	<b>33</b>
<hr/>		
<b>CHAPTER 2</b>	<b>MODELING PROCESS QUALITY</b>	<b>34</b>
2-1	Describing Variation	35
2-1.1	The Stem and Leaf Plot	35
2-1.2	The Frequency Distribution and Histogram	38
2-1.3	Numerical Summary of Data	40
2-1.4	The Box Plot	43
2-1.5	Sample Computer Output	44
2-1.6	Probability Distributions	46
2-2	Important Discrete Distributions	51
2-2.1	The Hypergeometric Distribution	51
2-2.2	The Binomial Distribution	52
2-2.3	The Poisson Distribution	55
2-2.4	The Pascal and Related Distributions	56

2-3	Important Continuous Distributions	57
2-3.1	The Normal Distribution	57
2-3.2	The Exponential Distribution	62
2-3.3	The Gamma Distribution	65
2-3.4	The Weibull Distribution	67
2-4	Some Useful Approximations	69
2-4.1	The Binomial Approximation to the Hypergeometric	69
2-4.2	The Poisson Approximation to the Binomial	69
2-4.3	The Normal Approximation to the Binomial	70
2-4.4	Comments on Approximations	70
2-5	Exercises	71

**CHAPTER 3 INFERENCES ABOUT PROCESS QUALITY 77**

3-1	Statistics and Sampling Distributions	78
3-1.1	Sampling from a Normal Distribution	79
3-1.2	Sampling from a Bernoulli Distribution	83
3-1.3	Sampling from a Poisson Distribution	84
3-2	Estimation of Process Parameters	85
3-2.1	Point Estimation	85
3-2.2	Interval Estimation	86
3-3	Hypothesis Testing on Process Parameters	96
3-3.1	Tests on Means, Variance Known	97
3-3.2	The Use of <i>P</i> -Values in Hypothesis Testing	100
3-3.3	Tests on Means of Normal Distributions, Variance Unknown	101
3-3.4	Tests on Variances of Normal Distributions	107
3-3.5	Tests on Binomial Parameters	109
3-3.6	Tests on Poisson Parameters	110
3-3.7	Probability Plotting	113
3-3.8	The Probability of Type II Error	116
3-4	Exercises	119

---

**PART II STATISTICAL PROCESS CONTROL 127**

---

**CHAPTER 4 METHODS AND PHILOSOPHY OF STATISTICAL PROCESS CONTROL 129**

4-1	Introduction	130
4-2	Chance and Assignable Causes of Quality Variation	130
4-3	Statistical Basis of the Control Chart	132
4-3.1	Basic Principles	132
4-3.2	Choice of Control Limits	138
4-3.3	Sample Size and Sampling Frequency	140

4-3.4	Rational Subgroups	143
4-3.5	Analysis of Patterns on Control Charts	146
4-3.6	Discussion of Sensitizing Rules for Control Charts	149
4-4	The Rest of the "Magnificent Seven"	150
4-5	Implementing SPC	158
4-6	An Application of SPC	159
4-7	Nonmanufacturing Applications of Statistical Process Control	167
4-8	Exercises	174

## CHAPTER 5 CONTROL CHARTS FOR VARIABLES 179

5-1	Introduction	180
5-2	Control Charts for $\bar{x}$ and $R$	181
5-2.1	Statistical Basis of the Charts	181
5-2.2	Development and Use of $\bar{x}$ and $R$ Charts	186
5-2.3	Charts Based on Standard Values	201
5-2.4	Interpretation of $\bar{x}$ and $R$ Charts	202
5-2.5	The Effect of Nonnormality on $\bar{x}$ and $R$ Charts	205
5-2.6	The Operating-Characteristic Function	206
5-2.7	The Average Run Length for the $\bar{x}$ Chart	209
5-3	Control Charts for $\bar{x}$ and $S$	211
5-3.1	Construction and Operation of $\bar{x}$ and $S$ Charts	212
5-3.2	The $\bar{x}$ and $S$ Control Charts with Variable Sample Size	217
5-3.3	The $S^2$ Control Chart	221
5-4	Control Charts for Individual Measurements	221
5-5	Summary of Procedures for $\bar{x}$ , $R$ , and $S$ Charts	229
5-6	Applications of Variables Control Charts	230
5-7	Exercises	235

## CHAPTER 6 CONTROL CHARTS FOR ATTRIBUTES 250

6-1	Introduction	251
6-2	The Control Chart for Fraction Nonconforming	251
6-2.1	Development and Operation of the Control Chart	253
6-2.2	Variable Sample Size	265
6-2.3	Nonmanufacturing Applications	270
6-2.4	The Operating-Characteristic Function and Average Run Length Calculations	271
6-3	Control Charts for Nonconformities (Defects)	275
6-3.1	Procedures with Constant Sample Size	275
6-3.2	Procedures with Variable Sample Size	285

6-3.3	Demerit Systems	287
6-3.4	The Operating-Characteristic Function	289
6-3.5	Dealing with Low Defect Levels	290
6-3.6	Nonmanufacturing Applications	294
6-4	Choice Between Attributes and Variables Control Charts	294
6-5	Guidelines for Implementing Control Charts	299
6-6	Exercises	304

**CHAPTER 7 CUMULATIVE SUM AND EXPONENTIALLY WEIGHTED MOVING AVERAGE CONTROL CHARTS 313**

7-1	The Cumulative-Sum Control Chart	314
7-1.1	Basic Principles: The Cusum Control Chart for Monitoring the Process Mean	314
7-1.2	The Tabular or Algorithmic Cusum for Monitoring the Process Mean	317
7-1.3	Recommendations for Cusum Design	322
7-1.4	The Standardized Cusum	324
7-1.5	Rational Subgroups	325
7-1.6	Improving Cusum Responsiveness for Large Shifts	325
7-1.7	The Fast Initial Response or Headstart Feature	325
7-1.8	One-Sided Cusums	327
7-1.9	A Cusum for Monitoring Process Variability	328
7-1.10	Cusums for Other Sample Statistics	329
7-1.11	The V-Mask Procedure	329
7-2	The Exponentially Weighted Moving-Average Control Chart	332
7-2.1	The Exponentially Weighted Moving-Average Control Chart for Monitoring the Process Mean	333
7-2.2	Design of an EWMA Control Chart	337
7-2.3	Rational Subgroups	339
7-2.4	Extensions of the EWMA	339
7-3	The Moving Average Control Chart	341
7-4	Exercises	344

**CHAPTER 8 OTHER STATISTICAL PROCESS CONTROL TECHNIQUES 348**

8-1	Statistical Process Control for Short Production Runs	349
8-1.1	$\bar{x}$ and $R$ Charts for Short Production Runs	349
8-1.2	Attribute Control Charts for Short Production Runs	352
8-1.3	Other Methods	353
8-2	Modified and Acceptance Control Charts	354
8-2.1	Modified Control Limits for the $\bar{x}$ Chart	354
8-2.2	Acceptance Control Charts	357

8-3	Group Control Charts for Multiple-Stream Processes	358
8-4	Multivariate Quality Control	360
8-4.1	Monitoring of Means	362
8-4.2	Monitoring Process Variability	372
8-5	SPC with Correlated Data	374
8-6	Interfacing Statistical Process Control and Engineering Process Control	386
8-6.1	Process Monitoring and Process Regulation	386
8-6.2	Combining SPC and EPC	395
8-7	Economic Design of Control Charts	399
8-7.1	Designing a Control Chart	399
8-7.2	Process Characteristics	399
8-7.3	Cost Parameters	400
8-7.4	Early Work and Semi-Economic Design	402
8-7.5	An Economic Model of the $\bar{x}$ Control Chart	403
8-7.6	Other Work	412
8-8	Overview of Other Procedures	413
8-8.1	Tool Wear	413
8-8.2	Control Charts Based on Other Sample Statistics	414
8-8.3	Adaptive Schemes	415
8-8.4	Selecting the Optimum Target Value for a Process	417
8-8.5	Fill Control	419
8-8.6	Precontrol	419
8-9	Exercises	421

## CHAPTER 9 PROCESS CAPABILITY ANALYSIS 430

9-1	Introduction	431
9-2	Process-Capability Analysis Using a Histogram or a Probability Plot	433
9-2.1	Using the Histogram	433
9-2.2	Probability Plotting	434
9-3	Process Capability Ratios	438
9-3.1	Use and Interpretation of PCR	438
9-3.2	Process-Capability Ratio for an Off-Center Process	442
9-3.3	Normality and the Process Capability Ratio	444
9-3.4	More About Process Centering	444
9-3.5	Confidence Intervals and Tests on Process Capability Ratios	447
9-4	Process-Capability Analysis Using a Control Chart	451
9-5	Process-Capability Analysis Using Designed Experiments	453
9-6	Gage and Measurement System Capability Studies	455

9-7	Setting Specification Limits on Discrete Components	461
9-7.1	Linear Combinations	461
9-7.2	Nonlinear Combinations	465
9-8	Estimating the Natural Tolerance Limits of a Process	467
9-8.1	Tolerance Limits Based on the Normal Distribution	468
9-8.2	Nonparametric Tolerance Limits	469
9-9	Exercises	470

---

<b>PART III</b>	<b>PROCESS DESIGN AND IMPROVEMENT WITH DESIGNED EXPERIMENTS</b>	<b>475</b>
-----------------	---	------------

---

<b>CHAPTER 10</b>	<b>THE FUNDAMENTALS OF EXPERIMENTAL DESIGN</b>	<b>477</b>
-------------------	--	------------

10-1	What is Experimental Design?	478
10-2	Examples of Designed Experiments in Quality and Process Improvement	479
10-3	Experiments with One Factor	483
10-3.1	An Example	483
10-3.2	The Analysis of Variance	485
10-3.3	Residual Analysis	490
10-3.4	Comparison of Individual Means	491
10-3.5	Using the Computer	494
10-3.6	A Components-of-Variance Model	496
10-4	Blocking and Nuisance Factors	499
10-4.1	The Randomized Block Design	499
10-4.2	Residual Analysis	504
10-5	Guidelines for Designing Experiments	506
10-6	Exercises	508

<b>CHAPTER 11</b>	<b>FACTORIAL AND FRACTIONAL FACTORIAL EXPERIMENTS FOR PROCESS DESIGN AND IMPROVEMENT</b>	<b>512</b>
-------------------	--	------------

11-1	Factorial Experiments	513
11-1.1	An Example	517
11-1.2	Statistical Analysis	517
11-1.3	Residual Analysis	523
11-2	The $2^k$ Factorial Design	525
11-2.1	The $2^2$ Design	525
11-2.2	The $2^k$ Design for $k \geq 3$ Factors	532
11-2.3	A Single Replicate of the $2^k$ Design	545
11-2.4	Addition of Center Points to the $2^k$ Design	549
11-2.5	Blocking and Confounding in the $2^k$ Design	553

11-3	Fractional Replication of the $2^k$ Design	555	
11-3.1	The One-Half Fraction of the $2^k$	555	
11-3.2	Smaller Fractions: The $2^{k-p}$ Fractional Factorial Design	562	
11-4	Exercises	569	
<b>CHAPTER 12</b>	<b>PROCESS OPTIMIZATION WITH DESIGNED EXPERIMENTS</b>		<b>572</b>
12-1	Response Surface Methods and Designs	573	
12-1.1	The Method of Steepest Ascent	575	
12-1.2	Analysis of a Second-Order Response Surface	578	
12-2	Evolutionary Operation	583	
12-3	Taguchi's Contributions to Quality Engineering	589	
12-3.1	The Taguchi Philosophy	590	
12-3.2	The Taguchi Approach to Parameter Design	591	
12-3.3	Improved Robust Parameter Design	600	
12-4	Exercises	601	
<hr/>			
<b>PART IV</b>	<b>ACCEPTANCE SAMPLING</b>		<b>605</b>
<b>CHAPTER 13</b>	<b>LOT-BY-LOT ACCEPTANCE SAMPLING FOR ATTRIBUTES</b>		<b>606</b>
13-1	The Acceptance Sampling Problem	607	
13-1.1	Advantages and Disadvantages of Sampling	608	
13-1.2	Types of Sampling Plans	609	
13-1.3	Lot Formation	610	
13-1.4	Random Sampling	610	
13-1.5	Guidelines for Using Acceptance Sampling	611	
13-2	Single-Sampling Plans for Attributes	613	
13-2.1	Definition of a Single-Sampling Plan	613	
13-2.2	The OC Curve	613	
13-2.3	Designing a Single-Sampling Plan with a Specified OC Curve	619	
13-2.4	Rectifying Inspection	621	
13-3	Double, Multiple, and Sequential Sampling	625	
13-3.1	Double-Sampling Plans	625	
13-3.2	Multiple-Sampling Plans	632	
13-3.3	Sequential-Sampling Plans	632	
13-4	Military Standard 105E (ANSI/ASQC Z1.4, ISO 2859)	636	
13-4.1	Description of the Standard	636	



13-4.2 Procedure 638  
 13-4.3 Discussion 643  
 13-5 The Dodge-Romig Sampling Plans 645  
     13-5.1 AOQL Plans 646  
     13-5.2 LTPD Plans 648  
     13-5.3 Estimation of Process Average 649  
 13-6 Exercises 649

**CHAPTER 14 OTHER ACCEPTANCE SAMPLING TECHNIQUES 652**

14-1 Acceptance Sampling by Variables 653  
     14-1.1 Advantages and Disadvantages of Variables Sampling 653  
     14-1.2 Types of Sampling Plans Available 654  
     14-1.3 Caution in the Use of Variables Sampling 655  
 14-2 Designing a Variables Sampling Plan with a Specified OC Curve 656  
 14-3 MIL STD 414 (ANSI/ASQC Z1.9) 659  
     14-3.1 General Description of the Standard 659  
     14-3.2 Use of the Tables 660  
     14-3.3 Discussion of MIL STD 414 and ANSI/ASQC Z1.9 663  
 14-4 Other Variables Sampling Procedures 664  
     14-4.1 Sampling by Variables to Give Assurance Regarding the Lot or Process Mean 664  
     14-4.2 Sequential Sampling by Variables 665  
 14-5 Chain Sampling 665  
 14-6 Continuous Sampling 667  
     14-6.1 CSP-1 668  
     14-6.2 Other Continuous Sampling Plans 670  
 14-7 Skip-Lot Sampling Plans 671  
 14-8 Exercises 675

**APPENDIX A-1**

I Cumulative Poisson Distribution A-3  
 II Cumulative Standard Normal Distribution A-6  
 III Percentage Points of the  $\chi^2$  Distribution A-8  
 IV Percentage Points of the  $t$  Distribution A-9  
 V Percentage Points of the  $F$  Distribution A-10

VI	Factors for Constructing Variables Control Charts	A-15
VII	Factors for Two-Sided Normal Tolerance Limits	A-16
VIII	Factors for One-Sided Normal Tolerance Limits	A-17
IX	Random Numbers	A-18

<b>BIBLIOGRAPHY</b>	<b>B-1</b>
---------------------	------------

<b>ANSWERS TO SELECTED EXERCISES</b>	<b>ANS-1</b>
--------------------------------------	--------------

<b>INDEX</b>	<b>I-1</b>
--------------	------------