
Permanent Magnet Synchronous and Brushless DC Motor Drives

R. Krishnan

*Electrical and Computer Engineering Department
Virginia Tech
Blacksburg, Virginia, U.S.A.*



CRC Press

Taylor & Francis Group

Boca Raton London New York

CRC Press is an imprint of the
Taylor & Francis Group, an **informa** business

Contents

Preface.....xvii
Acknowledgments.....xxi
Author xxiii
List of Symbols.....xxv

PART I Introduction to Permanent Magnets and Machines and Converters and Control

Chapter 1 Permanent Magnets and Machines 3

 1.1 Permanent Magnets 3

 1.1.1 Demagnetization Characteristics 5

 1.1.2 Operating Point and Air Gap Line 7

 1.1.3 Energy Density 10

 1.1.4 Energy Stored in the Magnet..... 12

 1.1.5 Magnet Volume 13

 1.1.6 Effect of External Magnetic Field Intensity 13

 1.1.6.1 Analytical Approach..... 14

 1.1.6.2 Graphical Approach..... 17

 1.2 Arrangement of PMs 21

 1.3 Magnetization of PMs 23

 1.3.1 Radial and Parallel Magnetizations 23

 1.3.2 Halbach Array 25

 1.4 PM ac Machines 31

 1.4.1 Machine Configurations 31

 1.4.2 PM Rotor Types..... 34

 1.4.2.1 Surface-Mounted PMSM..... 34

 1.4.2.2 Surface-Inset PMSM 34

 1.4.2.3 Interior PMSM..... 35

 1.4.2.4 Line-Start PMSM 37

 1.4.3 Hybrid Machines 38

 1.4.3.1 Flux Reversal PMSM..... 39

 1.4.3.2 Flux Switching Machine..... 42

 1.4.3.3 PM SRM or Doubly Salient PM Machine 43

 1.4.4 Concentrated Coil-Wound PMSMs 46

 1.4.5 Types of PMSMs 48

 1.5 Fundamentals of Synchronous Machines..... 51

 1.5.1 Principle of Operation 51

 1.5.2 MMF of a Coil 52

1.5.3	Sinusoidal MMF Distribution	53
1.5.3.1	Concentric Winding.....	53
1.5.3.2	Distributed Winding	53
1.5.4	Induced EMF.....	54
1.5.4.1	Winding Distribution Factor.....	57
1.5.4.2	Winding Pitch Factor.....	59
1.5.4.3	Skew Factor	61
1.5.4.4	Winding Factor	63
1.5.5	Types of Windings.....	64
1.5.5.1	Single-Layer Winding.....	64
1.5.5.2	Double-Layer Winding	64
1.5.6	Rotating Magnetic Field.....	66
1.5.6.1	Sinusoidal MMF Distribution.....	67
1.5.6.2	Rectangular MMF Distribution.....	71
1.6	Fundamental Synchronous Machine Relationships	71
1.6.1	Effective Air Gap	72
1.6.2	Effect of Magnet on Induced EMF	74
1.6.3	Electromagnetic Power and Torque.....	75
1.6.4	Fundamental Representation of Electromagnetic Torque.....	76
1.6.5	Machine Output Equation	78
1.6.6	Equivalent Magnet Current.....	81
1.6.7	Safe Peak Stator Current	82
1.6.8	Inductances.....	84
1.6.8.1	Self-Inductance per Phase.....	87
1.6.8.2	Magnetizing Inductance	87
1.6.8.3	Synchronous Inductance.....	88
1.6.8.4	d- and q-Axes Inductances	88
1.6.9	Effect of Stator Excitation on Air Gap Flux Density	89
1.7	Core Losses	92
1.7.1	Stator Core Losses.....	92
1.7.2	Eddy Current Losses	95
1.7.2.1	Eddy Current Loss in Tooth	96
1.7.2.2	Eddy Current Loss in Yoke	99
1.7.3	Evaluation of Peak Tooth and Yoke Flux Densities	100
1.7.4	Hysteresis Losses	101
1.7.5	Core Loss Measurement in the Machine.....	102
1.8	Resistive Losses.....	103
1.9	Initial Machine Design.....	105
1.10	Cogging Torque	107
1.10.1	Cause and Magnitude.....	107
1.10.2	Basics of Cogging Torque	107
1.10.2.1	General Expression for Cogging Torque	109

1.10.3	Analysis and Computation	110
1.10.4	Factors Affecting Cogging Torque.....	111
1.10.5	Mitigation Methods	111
1.10.5.1	Skewing	112
1.10.5.2	Varying Magnet Width	113
1.10.5.3	Varying Slot Width	114
1.10.5.4	Shifting Alternate Pair of Poles.....	114
1.10.5.5	Notching of Teeth	114
1.11	Basic Types of PMSMs Based on Flux Paths.....	115
1.12	Vibration and Noise.....	122
	References	123

Chapter 2	Introduction to Inverters and Their Control.....	135
2.1	Power Device.....	136
2.1.1	Power Devices and Switching	136
2.1.1.1	Power Diodes	136
2.1.1.2	MOSFET.....	137
2.1.1.3	Insulated Gate Bipolar Transistor.....	138
2.1.2	Switching of Power Devices.....	139
2.1.3	Device Losses.....	142
2.1.3.1	Conduction Loss	142
2.1.3.2	Switching Losses	143
2.2	DC Input Source.....	146
2.2.1	DC Input Source with Diode Bridge Rectifier	147
2.3	DC to ac Power Conversion.....	150
2.3.1	Single-Phase Half-Wave Inverter	150
2.3.2	Single-Phase Full-Wave Inverter.....	153
2.3.3	Three-Phase Inverter	155
2.4	Real Power.....	161
2.5	Reactive Power	161
2.6	Need for Inverter Control	162
2.7	Pulse Width Modulation.....	164
2.7.1	PWM Implementation	167
2.7.1.1	Reference Signal Generation	168
2.7.1.2	Sampling of Reference Signals	169
2.7.1.3	Transfer Characteristics of PWM- Controlled Inverters	171
2.7.1.4	Off-Line Optimized PWM	172
2.8	Hysteresis Current Control	173
2.9	Space Vector Modulation	176
2.9.1	Switching States of the Inverter	177
2.9.2	Principle of Space Vector Modulation	177
2.9.2.1	Transfer Characteristics of SVM- Controlled Inverters	183
2.9.3	Space Vector Modulator Implementation.....	188

2.9.4	Switching Ripple in SVM	188
2.9.4.1	Hybrid PWM Controller	192
2.10	Inverter Switching Delay	195
2.10.1	Control Modeling of the Three-Phase Inverter	207
2.11	Input Power Factor Correction Circuit	208
2.11.1	Single-Phase Power Factor Correction Circuit	208
2.11.2	Three-Phase Power Factor Correction Circuit	210
2.12	Four-Quadrant Operation	211
2.13	Converter Requirements	214
	References	215

PART II Permanent Magnet Synchronous Machines and Their Control

Chapter 3	Dynamic Modeling of Permanent Magnet Synchronous Machines	225
3.1	Real-Time Model of a Two-Phase PMSM	226
3.2	Transformation to Rotor Reference Frames	231
3.3	Three-Phase to Two-Phase Transformation	236
3.3.1	Unbalanced Operation	238
3.4	Zero Sequence Inductance Derivation	239
3.5	Power Equivalence	241
3.6	Electromagnetic Torque	242
3.7	Steady-State Torque Characteristics	244
3.8	Models in Flux Linkages	250
3.9	Equivalent Circuits	251
3.10	Per Unit Model	254
3.11	Dynamic Simulation	257
3.12	Small-Signal Equations of the PMSM	262
3.12.1	Derivation	262
3.13	Evaluation of Control Characteristics of the PMSM	264
3.13.1	Transfer Functions and Frequency Responses	264
3.14	Computation of Time Responses	266
3.15	Space Phasor Model	270
3.15.1	Principle	270
3.15.2	Model Derivation	270
	References	276
Chapter 4	Control Strategies for a Permanent Magnet Synchronous Machine	279
4.1	Vector Control	279
4.2	Derivation of Vector Control	280
4.2.1	Electromagnetic Torque	282

4.2.2	Stator d- and q-Axis Currents in Stator Reference Frames	283
4.2.3	Mutual Flux Linkages	283
4.2.4	Role of a Torque Angle in Machine Operations.....	284
4.2.5	Key Results.....	284
4.3	Drive System Schematic.....	285
4.3.1	Torque-Controlled Drive System	285
4.3.1.1	Hysteresis Current Controller	287
4.3.2	Simulation and Results of a Torque-Controlled Drive System	288
4.3.3	Speed-Controlled Drive System.....	293
4.3.3.1	Mutual Flux Programming.....	294
4.3.3.2	Torque Programming in the Flux-Weakening Region	294
4.3.4	Simulation and Results of a Speed-Controlled Drive System	296
4.4	Control Strategies	303
4.4.1	Constant ($\delta=90^\circ$) Torque Angle Control	304
4.4.2	Unity Power Factor Control.....	308
4.4.3	Constant Mutual Flux Linkages Control.....	312
4.4.4	Angle Control of Air Gap Flux and Current Phasors	314
4.4.5	Optimum Torque per Unit Current Control	317
4.4.6	Constant Power Loss Control.....	320
4.4.7	Maximum Efficiency Control	325
	References	328

Chapter 5	Flux-Weakening Operation	331
5.1	Maximum Speed	332
5.2	Flux-Weakening Algorithm.....	333
5.2.1	Indirect Control Scheme	336
5.2.2	Constant Torque Mode Controller.....	336
5.2.3	Flux-Weakening Controller	338
5.2.4	System Performance.....	339
5.3	Direct Flux Weakening	343
5.3.1	Maximum Permissible Torque Limit	344
5.3.2	Speed Control Scheme	344
5.3.3	Implementation Strategy	345
5.3.3.1	Lookup Tables Realization	346
5.3.4	System Performance.....	348
5.4	Parameter Sensitivity.....	349
5.4.1	Stator Resistance Variation	349
5.4.2	Rotor Flux Linkage Variation	350
5.4.3	q-Axis Inductance Variation	350
5.5	Model-Free (Parameter-Insensitive) Flux-Weakening Method.....	351

5.6	Six-Step Voltage and Constant Back EMF Control	
	Strategies for PMSM	353
5.6.1	Constant Back EMF Control Strategy.....	354
5.6.1.1	The Basics.....	354
5.6.1.2	Maximum Current in the Flux-Weakening Region	355
5.6.1.3	Operational Boundary	355
5.6.1.4	Maximum Speed in the Flux-Weakening Region	356
5.6.2	Six-Step Voltage Control Strategy.....	356
5.6.2.1	Fundamental Analysis	357
5.6.2.2	Steady-State Current in SSV Mode.....	359
5.6.2.3	Operational Boundary for the SSV Control Strategy.....	359
5.6.2.4	Comparison.....	360
5.7	Direct Steady-State Evaluation.....	361
5.7.1	Input Voltages.....	362
5.7.2	Machine Equations in State Space Form	365
5.7.3	Boundary Matching Condition and Solution	366
5.7.4	MATLAB® Program.....	369
5.8	Flux Weakening in SMPM and IPM Synchronous Machines	371
5.8.1	Flux-Weakening Equations in New Base	371
	References	376
Chapter 6	Design of Current and Speed Controllers	379
6.1	Current Controller	380
6.1.1	Rotor Reference Frame Current Controllers	381
6.1.2	Stator Reference Frames Current Controller.....	382
6.1.3	Deadbeat Current Controllers	385
6.1.3.1	Deadbeat Controller.....	385
6.1.3.2	Predictive Deadbeat Controller	386
6.1.3.3	Improved Predictive Deadbeat Controller.....	388
6.2	Speed Controller.....	389
6.2.1	Derivation of Block Diagram	390
6.2.2	Simplified Current Loop Transfer Function.....	391
6.2.3	Speed Controller.....	393
6.2.3.1	Smoothing.....	396
	References	398
Chapter 7	Parameter Sensitivity and Compensation.....	401
7.1	Introduction	401
7.1.1	Ratio of Torque to Its Reference.....	402
7.1.2	Ratio of Mutual Flux Linkages to Its Reference.....	403

7.2 Parameter Compensation through Air Gap Power
Feedback Control..... 404
7.2.1 Algorithm 405
7.2.2 Performance 408
7.3 Parameter Compensation by Reactive Power
Feedback Control..... 413
7.3.1 Principle of the Reactive Power Feedback
Compensation Scheme 414
7.3.2 Drive Schematic 414
7.3.3 Simulation Results..... 416
7.3.4 Comparison with Air Gap Power Feedback
Scheme 419
References 421

Chapter 8 Rotor Position Estimation and Position Sensorless Control..... 423
8.1 Current Model Adaptive Scheme 423
8.2 Sensing by External Signal Injection 428
8.2.1 Revolving Voltage Phasor Injection Scheme..... 428
8.2.2 Flux Linkage Injection in Rotating q-Axis 432
8.2.2.1 Algorithm..... 433
8.2.2.2 Demodulation 436
8.2.2.3 Observer..... 437
8.2.2.4 Implementation 438
8.2.2.5 Merits and Demerits of the Scheme 440
8.2.3 Alternating Voltage Phasor Injection 442
8.2.3.1 Sensorless Algorithm..... 442
8.2.3.2 Implementation 444
8.3 Current Model-Based Injection Scheme 447
8.4 Position Estimation Using PWM Carrier Components..... 448
8.4.1 Harmonic Voltage and Current Vectors 448
8.4.2 Rotor Position Estimation..... 449
8.4.3 Performance 450
References 451

**PART III Permanent Magnet Brushless DC
Machines and Their Control**

Chapter 9 PM Brushless DC Machine..... 457
9.1 Modeling of PM Brushless dc Motor 457
9.2 Normalized System Equations 460
9.3 The PMBDCM Drive Scheme..... 462
9.4 Dynamic Simulation..... 463
References 473

Chapter 10	Commutation Torque Ripple and Phase Advancing	475
10.1	Commutation Torque Ripple	476
10.2	Phase Advancing	480
10.3	Dynamic Modeling	481
10.3.1	Machine Equations	482
	References	494
Chapter 11	Half-Wave PMBDCM Drives	497
11.1	Split Supply Converter Topology	497
11.1.1	Operation of the PMBDC Motor with the Split Supply Converter	498
11.1.2	Operational Modes of the Converter	499
11.1.3	Merits and Demerits of the PMBDC Drive with the Split Supply Converter	501
11.1.4	Design Considerations for the PMBDC Motor	502
11.1.5	Impact of the Motor Inductance on the Dynamic Performance	504
11.1.6	Winding Connections	505
11.1.7	Drive System Description	506
11.1.8	Modeling, Simulation, and Analysis of the PMBDC Drive System	507
11.1.8.1	Modeling of the PMBDCM with Converter Modes	507
11.1.8.2	Modeling of the Speed Controller	508
11.1.8.3	Steering Circuit	509
11.1.8.4	Current Loop Modeling	510
11.1.8.5	Simulation and Analysis	510
11.1.8.6	Current Commutation Angle	511
11.1.8.7	Comparison of the Half-Wave and Full-Wave Inverter-Based PMBDC Drives	512
11.2	C-Dump Topology	513
11.2.1	Principle of Operation of the C-Dump PMBDC Drive System	514
11.2.1.1	Motoring Operation	514
11.2.1.2	Regenerative Operation	515
11.2.2	Analysis of the C-Dump PMBDCM Drive	516
11.2.2.1	Maximum Speed	516
11.2.2.2	Peak Recovery Current	517
11.2.2.3	Energy Recovery Capacitor	517
11.2.2.4	Energy Recovery Chopper	518
11.2.3	Comparison with Full-Wave Inverter-Controlled PMBDCM Drive	518

- 11.2.4 Modeling, Simulation, and Dynamic Performance 519
 - 11.2.4.1 Modeling 519
 - 11.2.4.2 System Performance 521
- 11.3 Variable dc Link Converter Topology 521
 - 11.3.1 Principle of Operation 522
 - 11.3.2 Motoring..... 524
 - 11.3.2.1 Regenerative Operation 524
 - 11.3.3 System Performance..... 525
 - 11.3.3.1 Torque Drive Performance 525
 - 11.3.3.2 Speed-Controlled Drive Performance 526
 - 11.3.4 Merits and Demerits..... 526
- 11.4 Variable Voltage Converter Topology with Buck-Boost Front-End..... 527
 - 11.4.1 Converter Circuit..... 527
 - 11.4.2 Operational Modes and Modeling of the PMBDC Motor Drive System 528
 - 11.4.3 Merits and Demerits..... 530
 - 11.4.4 Comparison with Full-Wave Inverter Drive..... 532
 - 11.4.5 Design of the Inductor and Output Capacitor in the Buck-Boost Front-End..... 532
 - 11.4.6 Control Strategies and Performance 534
 - 11.4.6.1 Strategy I—Open Loop Voltage Control 534
 - 11.4.6.2 Strategy II—Closed Loop Voltage Control 536
 - 11.4.6.3 Strategy III—Direct Phase Current Control 536
- References 538

- Chapter 12 Design of Current and Speed Controllers 541**
 - 12.1 Transfer Function of Machine and Load 541
 - 12.2 Inverter Transfer Function..... 544
 - 12.3 Transfer Functions of Current and Speed Controllers 544
 - 12.4 Current Feedback 544
 - 12.5 Speed Feedback..... 545
 - 12.6 Design of Controllers..... 545
 - 12.6.1 Current Controller 546
 - 12.6.2 First-Order Approximation of Inner Current Loop 548
 - 12.6.3 Speed Controller..... 549
 - References 553

Chapter 13	Sensorless Control of PMBDCM Drive	555
13.1	Current Sensing	555
13.2	Position Estimation	556
	References	559
Chapter 14	Special Issues	561
14.1	Torque Smoothing	561
14.2	Parameter Sensitivity of the PMBDCM Drive	562
14.3	Faults and Their Diagnosis	562
14.4	Vibration and Noise	562
	References	563
Index		565