

Data in Science and Technology

Editor in Chief: R. Poerschke

Magnetic Properties of Metals

d-Elements, Alloys and Compounds

Editor: H. P. J. Wijn

Springer-Verlag Berlin Heidelberg New York

London Paris Tokyo Hong Kong

Barcelona Budapest

Institut für Festkörperphysik

Fachgebiet 7.1: Theoretische Physik

Technische Universität Darmstadt

Hochschulstr. 6

D-6100 Darmstadt, FRG

Table of contents

List of symbols	IX
Definitions, units and conversion factors	XI
List of abbreviations	XII
1 3d elements	1
1.1 Ti, V, Cr, Mn	1
1.1.1 Ti	1
1.1.2 V	1
1.1.3 Cr	2
1.1.4 Mn	4
1.1.5 References for 1.1	6
1.2 Fe, Co, Ni	7
1.2.1 Phase diagrams, lattice constants	7
1.2.2 Paramagnetic properties	8
1.2.3 Spontaneous magnetization, magnetic moments and high-field susceptibility	10
1.2.4 Magnetocrystalline anisotropy constants	12
1.2.5 Magnetostriction coefficients	14
1.2.6 Magnetic moments and densities	15
1.2.7 Hyperfine fields	16
1.2.8 Spin wave properties	16
1.2.9 g factors	17
1.2.10 Fermi surfaces, band structures, exchange energies and electron spin polarizations	17
1.2.11 Kerr effect	19
1.2.12 References for 1.2	20
2 Alloys between 3d elements	22
2.1 Alloys between Fe, Co or Ni	22
2.1.1 Phase diagrams, lattice parameters	23
2.1.2 Paramagnetic properties	24
2.1.3 Hyperfine magnetic fields, isomer shifts	26
2.1.4 Spin waves	28
2.1.5 Atomic magnetic moment, g and g' factor	29
2.1.6 Spontaneous magnetization, Curie temperature	33
2.1.7 High-field susceptibility	36
2.1.8 Magnetocrystalline anisotropy	36
2.1.9 Magnetostriction	39
2.1.10 References for 2.1	41
2.2 Alloys between Ti, V, Cr or Mn	44
2.2.1 V-Ti	44
2.2.2 Cr-Ti	44
2.2.3 Cr-V	44
2.2.4 Mn-V	45
2.2.5 Mn-Cr	46
2.3 Alloys of Fe, Co or Ni and Ti, V, Cr or Mn	47
2.3.1 Fe-Ti	47
2.3.2 Fe-V	48
2.3.3 Fe-Cr	48
2.3.4 Fe-Mn	49
2.3.5 Co-Ti	50
2.3.6 Co-Cr	51
2.3.7 Co-Mn	52
2.3.8 Ni-Ti	52

2.3.9 Ni-V	52
2.3.10 Ni-Cr	53
2.3.11 Ni-Mn	53
2.3.12 Mn-V-Cr	55
2.3.13 Fe-V-Cr	55
2.3.14 Fe-Co-Ti	56
2.3.15 Fe-Co-Cr	56
2.3.16 Fe-Co-Mn	57
2.3.17 Fe-Ni-V	57
2.3.18 Fe-Ni-Cr	57
2.3.19 Fe-Ni-Mn	59
2.3.20 Co-Ni-Mn	60
2.3.21 References for 2.2 and 2.3	61
3 4d and 5d elements	63
3.1 Introduction to the paramagnetism of 4d and 5d transition metals	63
3.2 Magnetic susceptibility	64
3.3 References for 3	66
4 Alloys and compounds of 3d elements and 4d or 5d elements	68
4.1 3d elements and Zr, Nb, Mo or Hf, Ta, W, Re	68
4.1.1 Introduction	68
4.1.2 Ti and V alloys and compounds	68
4.1.3 Cr alloys and compounds	70
4.1.4 Mn alloys and compounds	71
4.1.5 Fe alloys and compounds	71
4.1.6 Co and Ni alloys and compounds	73
4.1.7 References for 4.1	74
4.2 3d elements and Ru, Rh, Pd or Os, Ir, Pt	76
4.2.1 3d-rich alloys	76
4.2.2 Concentrated alloys and intermetallic compounds	79
4.2.2.0 Introduction	79
4.2.2.1 Sc, Ti, and V alloys and compounds	80
4.2.2.2 Cr alloys and compounds	80
4.2.2.3 Mn alloys and compounds	81
4.2.2.4 Fe alloys and compounds	85
4.2.2.5 Co alloys and compounds	88
4.2.2.6 Ni alloys and compounds	89
4.2.3 4d- and 5d-rich alloys	90
4.2.4 References for 4.2	92
5 Alloys and compounds of 3d elements with main group elements	95
5.1 3d elements and Cu, Ag or Au	95
5.1.1 Tables and figures containing data on various alloys and compounds of the type 3d-(Cu, Ag, Au)	96
5.1.2 Data on individual alloys and compounds	99
5.1.2.1 3d-Cu	99
5.1.2.2 3d-Ag	103
5.1.2.3 3d-Au	104
5.1.3 References for 5.1	111
5.2 3d elements with Be, Mg or Zn	113
5.2.1 Alloys and compounds of 3d elements with Be	113
5.2.2 Alloys and compounds of 3d elements with Mg	115
5.2.3 Alloys and compounds of 3d elements with Zn	116
5.2.4 References for 5.2	117
5.3 3d elements and B, Al or Ga	118
5.3.1 Survey of tables and figures	118
5.3.2 3d-B alloys and compounds	120
5.3.3 3d-Al alloys and compounds	123

5.3.4 3d-Ga alloys and compounds	134
5.3.5 References for 5.3	142
5.4 3d elements and C, Si, Ge, Sn or Pb	145
5.4.1 Ti and V alloys and compounds	145
5.4.2 Cr alloys and compounds	146
5.4.3 Mn alloys and compounds	147
5.4.4 Fe alloys and compounds	151
5.4.5 Co and Ni alloys and compounds	156
5.4.6 References for 5.4	157
6 Alloys and compounds between 4d or 5d elements and main group elements	159
6.1 Compounds of Zr	159
6.2 Alloys and compounds of Nb	160
6.3 Compounds of Mo	162
6.4 Alloys and compounds of Pd	163
6.5 Compounds of Hf	164
6.6 Compounds of Ta	165
6.7 Compounds of W	165
6.8 Alloys and compounds of Pt	166
6.9 References for 6	167
7 Heusler alloys	168
7.1 Ferromagnets X_2MnZ with $X=d$ element	168
7.2 Antiferromagnets X_2MnZ with $X=3d$ element	169
7.3 Ferromagnets X_2YZ for $Y \neq Mn$	171
7.4 Paramagnets X_2YZ with $X, Y=3d$ element	172
7.5 References for 7	173
8 Metallic perovskites	174
8.1 Introduction	174
8.2 Magnetic and related data of $M^cX\text{Mn}\xi$ compounds	176
8.3 References for 8	179
Appendix: Contents of the volumes of the Landolt-Börnstein New Series (Group III, Vols. 19a-c) dealing with magnetic properties of metals based on d elements	181