TREATISE ON SOLID STATE CHEMISTRY

Volume 4 Reactivity of Solids

Edited by N. B. Hannay

Vice President Research and Patents Bell Laboratories Murray Hill, New Jersey

Jnv. – Nr. 4544

Bibliothek
d. Fachbereichs 8 der
Technischen Hochschule
Darmstadt

T179/4

PLENUM PRESS • NEW YORK-LONDON

_	oter 1 Ision		1
	A. D	. Le Claire	
1.	Intro	oduction	1
2.	The	Phenomenology of Diffusion	2
	2.1.	Fick's Laws	2
	2.2.	Self-Diffusion and Chemical Diffusion. The Kirkendall	
		Effect	6
	2.3.	Experimental Methods for Measuring Diffusion Co-	
		efficients	9
3.	2.4.	The Thermodynamic Description of Diffusion	18
3.	The	Atomic Theory of Diffusion	26
	3.1.		26
y . '	3.2.	Chemical Diffusion	28
-	3.3.	Self-Diffusion Correlation	30
	3.4.	The Theory of Atomic Jump Rates	40
Č)	3.5.	The Temperature and Pressure Dependence of $D \dots$	47
4.	Expe	erimental and Theoretical Results. A Brief Summary	51
e G	4.1.	Diffusion in Metals	51
į.	4.2.	Diffusion in Ionic Crystals	54
	Refe	erences	56

-	pter 2	- 4
Fact	tors Influencing the Reactivity of Solids	61
	Walter P. Gomes and Willy Dekeyser	
1.	General Outline	61
2.	Decomposition and Related Reactions	66
۷.	2.1. General	66
	2.2. The Effect of Mechanical Strain, Additives, and Pre-	00
	irradiation upon the Thermal Decomposition of an	
	Inorganic Compound: Ammonium Perchlorate	70
	2.3. The Role of Surface Impurities and of Shear Structures in	, •
	the Thermal Decomposition of Transition Metal Oxides.	71
	2.4. The Significance of Localized Energy Levels in the Photo-	
	lysis of Inorganic Compounds	72
	2.5. Topochemical Effects in the Photodimerization of Organic	. –
	Molecules	75
3.	Solid-Gas Reactions	77
	3.1. Tarnishing Reactions	77
	3.2. Other Reactions; The Role of Hydrogen Pressure and of	
	Vacancies in the Reduction of Additives in an Alkali	
	Halide Matrix	87
4.	Solid-Solid Reactions	89
	4.1. General	89
	4.2. Factors Influencing Solid-Solid Reactivity	90
5.	Solid-Liquid Reactions	94
	5.1. General	94
	5.2. Dissolution of Semiconductors: Influence of Conductivity	
	Type, Illumination, Applied Voltage, Crystal Face, and	
	Inhibitors in Solution	96
	5.3. The Role of Dislocations in Etching	99
6.	Reactions at the Surface of Solids	100
	6.1. Heterogeneous Catalysis	100
	6.2. Electrode Reactions.	104
7.	Conclusions	107
	References	108
~La	pter 3	
	n-Temperature Reactivity	115
b-	Karl E. Spear	
1.	Introduction	115
2.	Equilibrium Thermodynamics for High-Temperature Reactivity	117
	2.1. Free Energy Equations and Calculations	118
	2.2. Enthalpy and Entropy	129
	2.3. Thermodynamic Data Compilations	139

3.	Phase Diagrams and Chemical Reactions	144
	3.1. The Phase Rule	145
	3.2. Writing Chemical Equations	145
	3.3. High-Temperature Reactions	150
4.	General Behavior and Trends in High-Temperature Reactions.	157
,,	4.1. High-Temperature versus Room-Temperature Reactions	159
	4.2. Trends in Reaction Entropies	161
	4.3. Principle of Successive Entropy States	171
	4.4. Chemical Behavior of Solid–Gas Systems	175
	· · · · · · · · · · · · · · · · · · ·	180
-	4.5. Examples of Reaction Types in Solid-Gas Systems	
5.	Summary and Concluding Remarks	185
	Appendix: Sources of High-Temperature Thermodynamic Data	186
	Acknowledgments	187
	References	187
Cha	pter 4	
	omposition Reactions	193
	F. C. Tompkins	
1.	Introduction	193
2.	Dislocations and Enhanced Reactivity	194
3.	Kinetics of Solid Decomposition	199
4.	Nucleus Formation	200
	4.1. Single-Step Nucleation	200
	4.2. Multistep Nucleation	202
5.	Nucleus Growth	206
6.	Kinetic Equations of Nucleus Formation and Growth	207
7.	Exponential Acceleratory Period	212
8.	Abnormal Initial Growth	215
	8.1. Calculation of Normal Growth Constant	219
	8.2. The Induction Period	221
9.	Reversible Decompositions	224
10.	Aging	227
11.	General Discussion	229
	References	230
	pter 5	
	d-State Reactions	233
	Hermann Schmalzried	
. 1	Introduction	233
1.	1.1. General Remarks.	233
	1.2. Brief Summary of Defect Thermodynamics	235
	1.3. Some Aspects of the Phenomenological Diffusion Theory	233
	Relevant to Solid–Solid Reactions	238
9,	1.4. Descriptive Examples of Solid-State Reactions	242
	1.4. Descriptive Examples of Solid-State Reactions	∠ + ∠

2.	Cher	nical Reactions in the Solid State
	2.1.	Reactions between Atomic Defects
	2.2.	Reactions between Ionic Crystals
	2.3.	Reactions in and between Metals
3.	Spec	ial Solid-Solid Reactions
	3.1.	Powder Reactions
	3.2.	Topochemical Reactions
	3.3.	Double Reactions
	3.4.	Concluding Remarks
	Ackr	nowledgment
		rences
		•
Cha	pter 6	
Soli	d-Stat	e Electrochemistry
	Han	s Rickert
1.	Gen	eral Aspects of Solid Electrolytes
	1.1.	Disorder Equilibria in Solid Electrolytes and between
		Solid Electrolytes and the Environment
	1.2.	Transport Phenomena of Ions and Electrons in Solid
		Electrolytes
2.	Galv	vanic Cells with Solid Electrolytes for Thermodynamic
	Mea	surement
	2.1.	General Properties of Cells with Solid Electrolytes
	2.2.	Galvanic Cells with Solid Electrolytes for ΔG Measure-
		ments
	2.3.	Galvanic Cells with Solid Electrolytes for Activity
		Measurements
	2.4.	Coulometric Titration
3.	Galv	vanic Cells with Solid Electrolytes for Kinetic Investigations
	3.1.	Electrochemical Measurements of Oxygen Diffusion in
		Metals at High Temperatures using a Zirconia-Based
		Electrolyte
	3.2.	The Kinetics of the Formation of Solid Nickel Sulfide on
		Nickel at 400°C
	3.3.	Electrochemical Studies of the Transfer of Silver, Silver
	•	Ions, and Electrons across the Phase Boundary Solid
		Silver/Solid Silver Sulfide
	3.4.	Electrochemical Investigations of the Evaporation of
٠		Iodine from Copper Iodide
	3.5.	Electrochemical Knudsen Cells for Investigating the
		Thermodynamics of Vapors
	Refe	erences

	ographic Process
Frec	lerick C. Brown
Earl	y Developments
The	Emulsion System
	itometric Properties
Ioni	c Disorder in the Silver Halides
Elec	tron and Hole Mobility
	oelectric Effect in Emulsion Grains
Ultr	aviolet Response and Band Structure
Pho	non- and Disorder-Assisted Processes
Lum	inescence and Induced Absorption
Mec	hanism of Latent Image Formation
Ack	nowledgments
Refe	rences
pter 8	
	Reactions—Oxidation
Kar	Hauffe
	DORCHOD
Che	oduction misorption and Nucleation in the Initial Stage of Oxidation
Che Defe	misorption and Nucleation in the Initial Stage of Oxidation ect Structure of Halides, Oxides, and Sulfides
Che Defe 3.1.	misorption and Nucleation in the Initial Stage of Oxidation ect Structure of Halides, Oxides, and Sulfides Defect Structure in Silver Halides
Che Defe 3.1. 3.2.	misorption and Nucleation in the Initial Stage of Oxidation ect Structure of Halides, Oxides, and Sulfides Defect Structure in Silver Halides Defect Structure in p-Type Oxides and Sulfides
Che Defe 3.1. 3.2. 3.3.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides Defect Structure in Silver Halides Defect Structure in p-Type Oxides and Sulfides Defect Structure in n-Type Oxides and Sulfides
Che Defe 3.1. 3.2. 3.3. Gen	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides Defect Structure in Silver Halides Defect Structure in p-Type Oxides and Sulfides Defect Structure in n-Type Oxides and Sulfides eral Nature of Transport Processes in Ionic Crystals
Che Defe 3.1. 3.2. 3.3. Gen 4.1.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides Defect Structure in Silver Halides Defect Structure in p-Type Oxides and Sulfides Defect Structure in n-Type Oxides and Sulfides eral Nature of Transport Processes in Ionic Crystals Diffusion-Controlled Oxidation—The Parabolic Rate Law
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation.
Che Defe 3.1. 3.2. 3.3. Gen 4.1.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides Defect Structure in Silver Halides Defect Structure in p-Type Oxides and Sulfides Defect Structure in n-Type Oxides and Sulfides eral Nature of Transport Processes in Ionic Crystals Diffusion-Controlled Oxidation—The Parabolic Rate Law Local Cell Action during Metal Oxidation Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides Defect Structure in Silver Halides Defect Structure in p-Type Oxides and Sulfides Defect Structure in n-Type Oxides and Sulfides eral Nature of Transport Processes in Ionic Crystals Diffusion-Controlled Oxidation—The Parabolic Rate Law Local Cell Action during Metal Oxidation Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer Metal Oxidation with Simultaneous Diffusion of Oxygen
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal.
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. 4.4. Pha	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. Pha Line	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal. see Boundary Reactions and Evaporation of the Scale—The ear Rate Law.
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. 4.4. Pha Line Cata	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal. see Boundary Reactions and Evaporation of the Scale—The ear Rate Law
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. 4.4. Pha Line Cata Oxio	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal. see Boundary Reactions and Evaporation of the Scale—The ear Rate Law. astrophic Oxidation. de Layer Formation with Several Phases.
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. 4.4. Pha Line Cata Oxico Oxic	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal. se Boundary Reactions and Evaporation of the Scale—The ear Rate Law. astrophic Oxidation. de Layer Formation with Several Phases.
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. 4.4. Pha Line Cata Oxido Oxide 8.1.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal. see Boundary Reactions and Evaporation of the Scale—The ear Rate Law. astrophic Oxidation. de Layer Formation with Several Phases. dation of Alloys. The Semiconductor Valence Approach to Alloy Oxidation
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. 4.4. Pha Line Cata Oxid 8.1. 8.2.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal. se Boundary Reactions and Evaporation of the Scale—The ear Rate Law. astrophic Oxidation. de Layer Formation with Several Phases. dation of Alloys. The Semiconductor Valence Approach to Alloy Oxidation Selective Oxidation of Noble Alloys.
Che Defe 3.1. 3.2. 3.3. Gen 4.1. 4.2. 4.3. 4.4. Pha Line Cata Oxido Oxide 8.1.	misorption and Nucleation in the Initial Stage of Oxidation ext Structure of Halides, Oxides, and Sulfides. Defect Structure in Silver Halides. Defect Structure in p-Type Oxides and Sulfides. Defect Structure in n-Type Oxides and Sulfides. eral Nature of Transport Processes in Ionic Crystals. Diffusion-Controlled Oxidation—The Parabolic Rate Law. Local Cell Action during Metal Oxidation. Grain Boundary and Short-Circuit Diffusion in the Growing Oxide Layer. Metal Oxidation with Simultaneous Diffusion of Oxygen in the Metal. see Boundary Reactions and Evaporation of the Scale—The ear Rate Law. astrophic Oxidation. de Layer Formation with Several Phases. dation of Alloys. The Semiconductor Valence Approach to Alloy Oxidation

9. 10.	Passivity and Inhibition in High-Temperature Metal Oxidation Thin Oxide Layer Formation	44 44
	10.1. The Linear Rate Law	44
	10.2. A Cubic Rate Law	44
	10.3. Space-Charge Effects in Oxide Growth—The Fourth-	
	Power Rate Law	44
	10.4. Logarithmic and Reciprocal Logarithmic Rate Laws	45
11.	Concluding Remarks	45
	References	45
	pter 9	
Met	al-Liquid Reactions: Corrosion	45
	M. J. Pryor and R. W. Staehle	
		4.0
1.	Definitions of Corrosion	45
2.	Thermodynamic Considerations	45
3.	Kinetic Considerations	46
4.	Alloy Corrosion	47
	4.1. Dealloying	47
_	4.2. Other Significant Alloying Effects	47
5.	Passivity	48
	5.1. Anodic Passivation	48
,	5.2. Mechanism of Passivation	48
6.	Aggravating Factors in Corrosion	48
	6.1. Galvanic Corrosion	48
- 1	6.2. Crevice Corrosion	48
;	6.3. Concentration Cell Corrosion	48
	6.4. Erosion Corrosion	48
. . .	6.5. Corrosion in the Presence of Cyclic Stresses	49
7.	Control of Corrosion	49
	7.1. Cathodic Protection	49
	7.2. Anodic Protection	49
	7.3. Inhibition	49
0	7.4. Organic Coatings	50 50
8.	Morphology of Corrosion	50
	8.1. General Corrosion	
٥	8.2. Pitting	50 50
9.	Metallurgical Factors	5(
-	9.1. Introduction	5(
	9.3. Effects of Dislocations and Cold Work	
	9.4. Grain Boundaries	5
4.	9.5 Compositionally Different Phases	51 51
	7) A CHOOSHICHARD LIMETERI PRASES	•

xiv

9.6	Effect of Deformation on Corrosion Processes
9.7	U
9.8	
9.9	, ,
	ergranular and Interfacial Corrosion
	. Introduction
	2. Intergranular Corrosion in Sensitized Stainless Steel
	B. Exfoliation of Aluminum
	Intergranular Attach in the Absence of Precipitation
	5. Grain Boundary Fracture Simulated by Hydrogen Entry
	rironmentally Induced Cracking Phenomena
	. Introduction
	2. Organization of the Data
11.3	3. Fundamental Aspects of Environmental Effects on Crack
	Propagation
11.4	Phenomenological Influences on Stress Corrosion
	Cracking
	nowledgments
Rei	erences
itering	
itering	
ntering J. I	. Burke and J. H. Rosolowski
ntering J. I . Int	Burke and J. H. Rosolowski
. Int	Burke and J. H. Rosolowski oduction
J. I J. Int . Sin . Pho	Burke and J. H. Rosolowski roduction
J. Int. Sin	Burke and J. H. Rosolowski oduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase.
J. Int Sin Lic	Burke and J. H. Rosolowski coduction
J. Int. Sint. Photostal 3.1	Burke and J. H. Rosolowski roduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature
. Int . Sin . Pho Lic 3.1 3.2	coduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase Particle Joining Sintering Temperature e Driving Force for Sintering
J. Int. Sint. Photostal 3.1	coduction tering of Powdered Metals and Ceramics commenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature Poriving Force for Sintering The Kelvin Equation
. Int . Sin . Pho Lic 3.1 3.2 . Th 4.1	coduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase Particle Joining Sintering Temperature e Driving Force for Sintering The Kelvin Equation Curvature in Three Dimensions.
J. Int. Sin. Photos 3.1 3.2 Th 4.1 4.2	E. Burke and J. H. Rosolowski roduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature e Driving Force for Sintering The Kelvin Equation. Curvature in Three Dimensions. Application to Particle Joining and Pore Elimination
J. Int. Sin. Pho Lic. 3.1 3.2 Th 4.1 4.2 4.3	coduction
Int. Int. Sin. Pho. Lic. 3.1 3.2 Th 4.1 4.2 4.3 4.4	coduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase Particle Joining Sintering Temperature Priving Force for Sintering The Kelvin Equation Curvature in Three Dimensions Application to Particle Joining and Pore Elimination Importance of Grain Boundary Energy Powder Activity
J. Int. Sin. Pho Lic. 3.1 3.2 4.1 4.2 4.3 4.4 4.5 Gr	coduction tering of Powdered Metals and Ceramics commenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature Driving Force for Sintering The Kelvin Equation Curvature in Three Dimensions. Application to Particle Joining and Pore Elimination Importance of Grain Boundary Energy Powder Activity Ain Growth during Sintering
Int . Int . Sin . Pho Lic 3.1 3.2 . Th 4.1 4.2 4.3 4.45 . Gr	coduction tering of Powdered Metals and Ceramics commenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature Driving Force for Sintering The Kelvin Equation. Curvature in Three Dimensions. Application to Particle Joining and Pore Elimination Importance of Grain Boundary Energy Powder Activity In Growth during Sintering. Particle Growth during the Early Stages of Sintering.
Int. Sin. Sin. 2. Int. 3.1 3.2 4.3 4.4 4.5 Gr 5.1 5.2	coduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature e Driving Force for Sintering The Kelvin Equation. Curvature in Three Dimensions. Application to Particle Joining and Pore Elimination Importance of Grain Boundary Energy Powder Activity ain Growth during Sintering. Particle Growth during the Early Stages of Sintering. Grain Boundary Motion in Solids.
Int . Int . Sin . Pho Lic 3.1 3.2 . Th 4.1 4.2 4.3 4.45 . Gr	coduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase Particle Joining Sintering Temperature Driving Force for Sintering The Kelvin Equation Curvature in Three Dimensions Application to Particle Joining and Pore Elimination Importance of Grain Boundary Energy Powder Activity In Growth during Sintering Particle Growth during the Early Stages of Sintering Grain Boundary Motion in Solids Interactions between Pores or Other Inclusions and Grain
J. I . Int . Sin . Pho Lic 3.1 3.2 . Th 4.1 4.2 4.3 4.4 4.5 . Gr 5.1 5.2 5.3	coduction tering of Powdered Metals and Ceramics enomenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature e Driving Force for Sintering The Kelvin Equation. Curvature in Three Dimensions. Application to Particle Joining and Pore Elimination Importance of Grain Boundary Energy Powder Activity ain Growth during Sintering. Particle Growth during the Early Stages of Sintering. Grain Boundary Motion in Solids. Interactions between Pores or Other Inclusions and Grain Boundaries
Int Sin Alice Sin	coduction tering of Powdered Metals and Ceramics momenological Description of Sintering in the Absence of a uid Phase. Particle Joining Sintering Temperature Driving Force for Sintering The Kelvin Equation Curvature in Three Dimensions. Application to Particle Joining and Pore Elimination Importance of Grain Boundary Energy Powder Activity In Growth during Sintering Particle Growth during the Early Stages of Sintering Grain Boundary Motion in Solids. Interactions between Pores or Other Inclusions and Grain Boundaries Exaggerated Grain Growth

6.	Othe	er Sintering Modes	64
	6.1.	Liquid-Phase Sintering	64
	6.2.	Hot Pressing	64
	6.3.	Reaction Sintering	64
7.	Theo	ory of Sintering	64
	7.1.	Driving Force and Mechanisms	64
	7.2.	Common Characteristics of Sintering Models	64
	7.3.	Development of Microstructure	65
	7.4.	Sintering Stages	65
	7.5.	Initial-Stage Sintering Models	65
	7.6.	Intermediate-Stage Sintering Models	65
	7.7.	Final-Stage Sintering Models	65
8.	Sum	mary	65
		nowledgment	65
	Refe	rences	65
		•	
Cha	pter 1	1	
Rea	ctions	of Solid Polymers	66
	F. A	. Bovey	
		·	
1.	Intro	oduction	66
	1.1.	The Chain Structure of Addition Polymers	66
	1.2.	Molecular Weight Distribution	66
	1.3.	Chain Conformation and Polymer Morphology	66
	1.4.	Types of Polymer Reactions	67
2.	Chai	n Scission and Cross-Linking; General	67
	2.1.	Effects of Chain Scission	67
	2.2.	Effects of Cross-Linking	67
	2.3.	Simultaneous Scission and Cross-Linking	67
3.		radation and Oxidation	67
•	3.1.	Thermal Degradation	67
	3.2.	Oxidative Degradation	68
	3.3.	Ozone Degradation	68
	3.4.	Flammability	68
	3.5.	Chemical Degradation	69
4.	Cros	s-Linking	69
	4.1.	Cross-Linking and Mechanical Properties	69
	4.2.	Cross-Linking Reactions	69
5.	Effec	ets of Radiation	70
	5.1.	Ultraviolet Photooxidation	70
	5.2.	High-Energy Radiation	70
	5.3.	Photoresists and Electron-Resists	70

6.	Reactions under Mechanical Stress	710
	References	711
Inde	x	715