

# Fatigue and Fracture in Steel Bridges

CASE STUDIES

JOHN W. FISHER

Professor of Civil Engineering  
Fritz Engineering Laboratory  
Lehigh University

A WILEY-INTERSCIENCE PUBLICATION

**JOHN WILEY & SONS**

New York · Chichester · Brisbane · Toronto · Singapore

# Contents

## *Abbreviations and Symbols*

xvii

## **1 INTRODUCTION**

1

- 1.1 General Overview, 1
- 1.2 Fracture Mechanics of Crack Growth, 4
- 1.3 Fatigue Crack Growth Model, 8
- 1.4 Damage Accumulation, 9
- 1.5 Crack Extension Behavior, 11
- 1.6 Summary, 12

## **PART I FATIGUE AND FRACTURE OF STRUCTURAL MEMBERS AT DETAILS OR LARGE DEFECTS**

## **2 EYEBARS AND PIN PLATES**

18

- 2.1 Fracture Analysis of Point Pleasant ("Silver") Bridge over the Ohio River, 20
  - 2.1.1 Description and History of the Bridge, 20
  - 2.1.2 Failure Modes and Analysis, 25
  - 2.1.3 Conclusions, 32
- 2.2 Illinois Route 157 over St. Clair Avenue, 33
  - 2.2.1 Description and History of the Bridge, 33
  - 2.2.2 Failure Modes and Analysis, 34
  - 2.2.3 Conclusions, 38
  - 2.2.4 Repair and Retrofit, 39

xi

<b>3 COVER-PLATED BEAMS AND FLANGE GUSSETS</b>	<b>41</b>
3.1 Fatigue-Fracture Analysis of Yellow Mill Pond Bridge at Bridgeport, Connecticut, 42	
3.1.1 Description and History of the Bridge, 42	
3.1.2 Failure Modes and Analysis, 48	
3.1.3 Conclusions, 57	
3.1.4 Repair and Fracture Control, 60	
<b>4 WEB CONNECTION PLATES</b>	<b>61</b>
4.1 Fatigue-Fracture Analysis of Lafayette Street Bridge, 62	
4.1.1 Description and History of the Bridge, 62	
4.1.2 Failure Modes and Analysis, 67	
4.1.3 Conclusions, 74	
4.1.4 Actual Repair and Fracture Control, 74	
<b>5 TRANSVERSE GROOVE WELDS</b>	<b>77</b>
5.1 Fatigue-Fracture Analysis of Aquasabon River Bridge, 78	
5.1.1 Description and History of the Bridge, 78	
5.1.2 Failure Modes and Analysis, 83	
5.1.3 Conclusions, 87	
5.1.4 Actual Repair and Fracture Control, 87	
5.2 Fatigue-Fracture Analysis of Quinnipiac River Bridge, 88	
5.2.1 Description and History of the Bridge, 88	
5.2.2 Failure Modes and Analysis, 91	
5.2.3 Conclusions, 104	
5.2.4 Repair and Fracture Control, 105	
5.3 Fatigue-Fracture Analysis of U.S. 51 over the Illinois River at Peru, 105	
5.3.1 Description and History of Bridge, 105	
5.3.2 Failure Modes and Analysis, 110	
5.3.3 Conclusions, 113	
5.3.4 Repair and Fracture Control, 113	

<b>6 WEB PENETRATIONS</b>	<b>116</b>
6.1 Fatigue-Fracture Analysis of the Dan Ryan Rapid Transit Steel Box Bents, 117	
6.1.1 Description and History of the Structure, 117	
6.1.2 Failure Modes and Analysis, 121	
6.1.3 Conclusions, 131	
6.1.4 Repair and Fracture Control, 131	
<b>7 WELDED HOLES</b>	<b>133</b>
7.1 Fatigue-Fracture Analysis of County Highway 28 Bridge over I-57 at Farina, Illinois, 133	
7.1.1 Description and History of the Bridge, 133	
7.1.2 Failure Modes and Analysis, 135	
7.1.3 Conclusions, 146	
7.1.4 Repair and Fracture Control, 146	
<b>8 CONTINUOUS LONGITUDINAL WELDS</b>	<b>148</b>
8.1 Fatigue-Fracture Resistance of the Gulf Outlet Bridge, 149	
8.1.1 Description and History of the Bridge, 149	
8.1.2 Crack Conditions and Analysis, 152	
8.1.3 Conclusions, 163	
8.1.4 Repair and Fracture Control, 163	
<b>9 LAMELLAR TEARING</b>	<b>165</b>
9.1 Fatigue-Fracture Analysis of Ft. Duquesne Bridge Rigid Frame Supports, 166	
9.1.1 Description and History of the Bridge, 166	
9.1.2 Failure Modes and Analysis, 171	
9.1.3 Conclusions, 176	
9.1.4 Repair and Fracture Control, 176	

**PART II SECONDARY STRESSES AND  
DISTORTION-INDUCED STRESS**

- 10 CANTILEVER FLOOR-BEAM BRACKETS 183**
- 10.1 Cracking of the Tie Plates of the Lehigh River and Canal Bridges, 184
- 10.1.1 Description and History of the Bridge, 184
  - 10.1.2 Failure Modes and Analysis, 186
  - 10.1.3 Conclusions, 193
  - 10.1.4 Repair and Fracture Control, 194
- 10.2 Cracking of Tie Plates of the Allegheny River Bridge, 195
- 10.2.1 Description and History of the Bridge, 195
  - 10.2.2 Failure Modes and Analysis, 198
  - 10.2.3 Conclusions, 204
  - 10.2.4 Repair and Fracture Control, 205
- 11 TRANSVERSE STIFFENER WEB GAPS 206**
- 11.1 Fatigue Analysis of Cracking in I-90 Bridge over Conrail Tracks in Cleveland, 207
- 11.1.1 Description and History of the Bridge, 207
  - 11.1.2 Failure Modes and Analysis, 207
  - 11.1.3 Conclusions, 217
  - 11.1.4 Repair and Fracture Control, 218
- 11.2 Fatigue Analysis of I-480 Cuyahoga River Bridge, 219
- 11.2.1 Description and History of the Bridge, 219
  - 11.2.2 Failure Modes and Analysis, 222
  - 11.2.3 Conclusions, 232
  - 11.2.4 Repair and Fracture Control, 233
- 12 FLOOR-BEAM CONNECTION PLATES 235**
- 12.1 Fatigue Cracking of the Poplar Street Bridge Approaches, 236
- 12.1.1 Description and History of the Bridge, 236
  - 12.1.2 Failure Modes and Analysis, 239
  - 12.1.3 Conclusions, 247
  - 12.1.4 Repair and Fracture Control, 248

- 12.2 Fatigue Cracking of the Polk County Bridge  
(Des Moines), 251
  - 12.2.1 Description and History of the Bridge, 251
  - 12.2.2 Failure Modes and Analysis, 254
  - 12.2.3 Conclusions, 257
  - 12.2.4 Repair and Fracture Control, 259
  
- 13 DIAPHRAGM CONNECTION PLATES 262**
- 13.1 Fatigue Cracking of the Belle Fourche River Bridge, 266
  - 13.1.1 Description and History of the Bridge, 266
  - 13.1.2 Failure Analysis, 271
  - 13.1.3 Conclusions, 271
  - 13.1.4 Repair and Fracture Control, 272
- 13.2 Fatigue Cracking of Chamberlain Bridge over Missouri  
River, 272
  - 13.2.1 Description and History of the Bridge, 272
  - 13.2.2 Failure Analysis, 275
  - 13.2.3 Conclusions, 277
  - 13.2.4 Repair and Fracture Control, 278
  
- 14 TIED ARCH FLOOR BEAMS 279**
- 14.1 Fatigue Cracking of Prairie Du Chien Bridge Floor  
Beams, 280
  - 14.1.1 Description and History of the Bridge, 280
  - 14.1.2 Failure Analysis, 284
  - 14.1.3 Conclusions, 287
  - 14.1.4 Repair and Fracture Control, 287
  
- 15 STRINGER-TO-FLOOR BEAM (TRUSS) BRACKETS 290**
- 15.1 Fatigue Cracking of the Stringer Webs of Walt Whitman  
Bridge, 291
  - 15.1.1 Description and History of the Bridge, 291
  - 15.1.2 Failure Modes and Analysis, 294
  - 15.1.3 Conclusions, 300
  - 15.1.4 Repair and Fracture Control, 301

**16 COPED MEMBERS**

30

16.1 *Fatigue Cracking at Stringer Copes of Bridge 51.5  
Windermere Subdivision, 303*

16.1.1 Description and History of the Bridge, 303

16.1.2 Failure Modes and Analysis, 303

16.1.3 Conclusions, 309

16.1.4 Repair and Fracture Control, 310

**AUTHOR INDEX**

3

**SUBJECT INDEX**

3